Scope of	Work for Property Lo	cated a	ıt:		<u>3713</u>	North 15th Street	
_	Property is: Single Far	nily 🖸	Duple	ex		Other	
Date:	9/15/2015				TI 0:	to CARL II all D. I. I. A. A. A.	 
ake no respo		after the i	nspection	dat	e, or for	ty of Milwaukee, the Redevelopment Author omissions through error or oversight. The I k Grant or HOME programs.	
Exterior	Condition Report						
Location Site	Required Work Landscaping	n/a	] Yes ⊡	7		Comments ees/brush away from house foundation	\$ Cost 600.00
	Steps/Handrails	n/a	Yes [	<b>4</b>	at alley	l .	\$ 900.00
	Service walks	n/a 🕓	Yes [				\$
	Fencing	n/a	Yes [				\$
	Parking	n/a 🕓	Yes				\$
	Retaining walls	n/a √	Yes				\$
	Other	n/a	Yes [	<b>√</b>	fill w/c	oncrete or remove ash box at alley	\$ 1,200.00
	Other	n/a	Yes [				\$
Garage	Singles: repair	n/a	Yes [				\$
	Shingles: Roof over existing	n/a	Yes [				\$
	Shingles:Tear off & re-roof	n/a	Yes [				\$ 
	Gutters/downspouts	n/a	Yes				\$
	Flashing	n/a	Yes [				\$
	Eaves	n/a	Yes [				\$
	Siding	n/a	Yes				\$
	Doors	n/a	Yes				\$
	Windows	n/a	Yes [				\$
	Slab	n/a	Yes				\$
	Paint	n/a	Yes				\$
	Electrical	n/a	Yes				\$
Davahaa	Other	n/a	Yes 🖸	<b>√</b>	guardr	ail @ parking slab (permit req.)	\$ 800.00
Porches	Roof	n/a 🕓	Yes [				\$
	Deck-upper	n/a 🖸	Yes [				\$
	Decklower	n/a	Yes [				\$
	Steps/handrails	n/a	Yes [	<b>✓</b>			\$ 750.00
	Ceiling	n/a 🕓	Yes [				\$
	Guardrails	n/a 🕓	Yes [				\$
	Structural	n/a	Yes [		_		\$ 
	Paint	n/a	Yes [				\$

n/a 🗌 Yes 🗹 **permit** 

Other

85.00

\$

## House

Chimney	n/a ☐ Yes ☑	\$ 45	0.00
Shingles: repair	n/a ☑ Yes 🗌	\$	
Shingles: Roof over existing	n/a ☑ Yes □	\$	
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 9,00	00.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 1,00	08.00
Flashing	n/a ☑ Yes □	\$	
Eaves	n/a 🗌 Yes 🗹 <b>fascia/soffit</b>	\$ 90	0.00
Siding	n/a ☐ Yes ☑	\$ 4,00	0.00
Storm Doors	n/a ☑ Yes □	\$	
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 70	00.00
Storm Windows	n/a ☑ Yes □	\$	
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 9,30	0.00
Paint	n/a  Yes  previously painted surfaces	\$ 2,20	00.00
Foundation	n/a ☑ Yes □	\$	
Electrical	n/a Yes vervice	\$ 1,00	00.00
Other	n/a 🗌 Yes 🗌	\$	
Other	n/a 🗌 Yes 🗌	\$	
Other	n/a 🗌 Yes 🗌	\$	
Other	n/a 🗌 Yes 🗌	\$	

Exterior: Estimated Cost:\* \$
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

32,893.00

Interior Co	unit: Entire unit (single family)	<b>7</b>		Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work			Other $\Box$	
	Repair/replace boiler	n/a ✓	Yes [	]	\$
	Repair radiation	n/a ✓	Yes	]	\$
	Repair/replace furnace	n/a	Yes [	assumed-no basement access	\$ 3,080.00
	Repair ductwork	n/a	Yes [		\$ 600.00
	Replace thermostat	n/a 🗌	Yes [		\$ 100.00
	Repair/replace grilles	n/a	Yes [		\$ 80.00
	Other	n/a	Yes [	permit	\$ 85.00
Electrical	Repair/replace receptacles	n/a 🗌	Yes 🖸		\$ 800.00
	Repair/replace switches	n/a 🗌	Yes [	<u> </u>	\$ 800.00
	Repair/replace fixtures	n/a 🗌	Yes [	<u> </u>	\$ 800.00
	Install outlets and circuits	n/a ✓	Yes [	]	\$
	Install outlets and circuits	n/a ✓	Yes	]	\$
	Install outlets and circuits	n/a ✓	Yes [	]	\$
	Install outlets and circuits	n/a ✓	Yes	]	\$
	Upgrade service	n/a 🗌	Yes [		\$ 1,749.00
	Other	n/a 🗌	Yes [	permit	\$ 85.00
DI	Other	n/a	Yes [	]	\$ 
Plumbing	Repair/replace kitchen sink	n/a 🗌	Yes [	]	\$
	Repair/replace kitchen sink fauce	n/a	Yes [	]	\$
	Repair/replace tub	n/a	Yes [	]	\$
	Repair/replace tub faucet	n/a	Yes	]	\$
	Repair/replace toilet	n/a 🗌	Yes [	]	\$
	Repair/replace lavatory	n/a 🗌	Yes [	]	\$
	Repair/replace lavatory faucet	n/a 🗌	Yes [	]	\$
	Repair/replace wash tub	n/a	Yes	]	\$
	Repair/replace wash tub faucet	n/a 🗌	Yes [	]	\$
	Other	n/a	Yes [	permit	\$ 85.00
	Repair drain/waste/vent piping	n/a	Yes [		\$ 700.00
	Repair water piping	n/a	Yes [		\$ 800.00
	Repair/replace water heater	n/a	Yes [	assumed-no basement access	\$ 1,300.00
	Other	n/a	Yes [	complete kitchen	\$ 1,455.00

n/a Yes complete bathroom

2,170.00

Other

Windows										
	Replace broken glass	n/a	<b>V</b>	Yes			\$			
	Repair or replace sash	n/a	<b>V</b>	Yes			\$			
Doors										
	Repair or replace doors	n/a		Yes	J		\$	950.00		
	Repair or repl. locks/latches	n/a		Yes	<b>✓</b>	Self Help	\$	330.00		
Walls/Ceiling	-									
	Repair or repl. @ defective	n/a		Yes	J		\$	4,800.00		
Paint										
	Repair or repl. @ defective	n/a		Yes	✓		\$	2,400.00		
Fire Safety										
	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>✓</b>	Self Help	\$	55.00		
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>V</b>	Self Help	\$	165.00		
	Install smoke/CO alarm: 2nd flr.	n/a	<b>V</b>	Yes		Self Help	\$			
Handrails										
04-1	Repair/replace defective	n/a		Yes	<b>√</b>	Self Help	\$	248.00		
Stairs	Repair defective	n/a		Yes	<b>V</b>	to basement	\$	864.00		
Floors	5	,		.,			•	2 222 22		
Other	Repair defective	n/a		Yes	1		\$	3,600.00		
Other		n/a		Yes			\$			
		n/a		Yes			\$			
		n/a		Yes			\$			
		n/a		Yes			\$			
						Interior: Estimated Cost:	\$	28,101.00		
						Total Exterior and Interior Cost:*	\$	60,994.00		
					*average contracted cost. Actual costs may vary. Self help will reduce the amount.					

## Date: 9/10/15 Inspected by: Tom Frank

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.